

Date: 12-05-24

Region: 4C

FEMS/CSS No.: 2965965

FAC ID: WV005

Maximo WO No.: 17364

Asset #:

Priority:  1



**Original Work Request:**

No heat call, Daikin system throwing 2 error codes, tried to reset, but did not work. Error code reads E5 and JA.

**Description of Repairs Needed:**

Investigate and troubleshoot emergency repair concern regarding error codes on Daikin system. Follow up trip to leak test system, including recover refrigerant, pull vacuum and recharge Daikin unit.

Labor:	Labor Hrs	Labor Rate	Total
Tech (1) - Initial Investigation	7.5	\$ 156.00	\$ 1,170.00
Trip Charge	1	\$ 157.50	\$ 157.50
Tech (2) - Leak Check System	13.5	\$ 156.00	\$ 2,106.00
Trip Charge	2	\$ 157.50	\$ 315.00

Material List:	Quantity	Cost	Total
Misc Parts - Recovery cylinder, nitrogen	1	\$ 550.00	\$ 550.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$3,748.50	\$550.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$4,298.50	\$515.82	\$257.91	\$5,072.23