

Date: 11-25-24

Region: 4C

FEMS/CSS No.: 2965965

FAC ID: WV005

Maximo WO No.: 17365

Asset #:

Priority:  1



**Original Work Request:**

No heat call, Daikin system throwing 2 error codes, tried to reset, but did not work. Error codes read - E5 and JA.

**Description of Repairs Needed:**

Proposal is NTE labor quote to locate leak. Investment is to recover refrigerant, leak check, pull a vacuum and recharge Daikin VRF condensing unit-2 (M# REYQ96; S# A000151). A repair quote will follow after leak identified.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	24	\$ 138.00	\$ 3,312.00
Tech (1)	24	\$ 120.00	\$ 2,880.00
Trip Charge	120	\$ 1.75	\$ 210.00

**Material List:**

	Quantity	Cost	Total
Misc Parts - Recovery cylinder, nitrogen	1	\$ 540.00	\$ 540.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$6,402.00	\$540.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$6,942.00	\$833.04	\$416.52	\$8,191.56