

Date: 1-15-25

Region: 4C

FAC ID: WV005

FEMS/CSS No.: 2965965

Maximo WO No.: 17904



Asset #:

Priority: 1

Original Work Request:

Repair - No heat call, Daikin System throwing 2 error codes, tried to reset, but did not work. Error codes read - E5 and JA.

Description of Repairs Needed:

Proposal is to recover refrigerant, replace the capillary tube that is leaking and pull a vacuum and recharge Daikin VRF Condensing Unit #2 (M# REYQ144; S# A000243)

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	24	\$ 138.00	\$ 3,312.00
Travel	4	\$ 138.00	\$ 552.00
Trip Charge	120	\$ 1.75	\$ 210.00

Material List:

	Quantity	Cost	Total
Capillary Tube (2462440)	1	\$ 233.70	\$ 233.70
Misc Parts - Recovery Tank, Nitrogen, Vacuum Pump Oil	1	\$ 58.50	\$ 58.50
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$4,074.00	\$292.20	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$4,366.20	\$523.94	\$261.97	\$5,152.12