

Date: 12-17-25

Region: 4C

FEMS/CSS No.: 3433186

FAC ID: WV005

Maximo WO No.: 20921

Asset #:

Priority:  1



**Original Work Request:**

No heat in offices (Zone 2) Daikin system Zone 2 has an E2 error code. Recommended contractor: Casto

**Description of Repairs Needed:**

Proposal is for labor to troubleshoot and diagnose the issues with the Daikin Zone 2 office area heating system. Found that the inverter board and compressor are bad and need to be replaced. Will quote customer on needed repairs

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	4.565	\$ 140.00	\$ 639.00
Trip Charge	1	\$ 105.00	\$ 105.00
			\$ -

**Material List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

**Equipment List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$744.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$744.00	\$89.28	\$44.64	\$877.92