

Date: 7/5/2023

Region: 4C  
FAC ID: WV006

CSS No.: 93353  
Maximo WO No.: 12795

Asset #:

Priority:  3



**Original Work Request:**

Fire extinguisher covers on many of the boxes in the wall need new plastic covers in the training building. They have had new extinguishers put in and need what I would call a bubble cover. The old flat covers have been removed.

**Description of Repairs Needed:**

Replace FE covers

**Labor:**

	Labor Hrs	Labor Rate	Total
1 Tech	1.5	\$ 100.00	\$ 150.00
			\$ -

**Material List:**

	Quantity	Cost	Total
FE Bubble Covers (CB-0722)	5	\$ 55.97	\$ 279.85
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

**Equipment List:**

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$150.00	\$279.85	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$429.85	\$51.58	\$25.79	\$507.22