

Date: 1-4-24

Region: 4C

CSS No.: 95037

FAC ID: WV006

Maximo WO No.: 14782



Asset #: [Redacted]

Priority: 1

Original Work Request:

The mini split A/C unit that cools the Marines area has a line set that runs from Marine area to the drill hall thru the main lobby of training building. The line set is sweating and casing ceiling tile damage, it appears that the line set needs to be insulated better and taped at the joints to stop leaking.

Description of Repairs Needed:

Investigated and repaired bad places in the armor flex, replaced pipe insulation and replaced damaged/stained ceiling tiles. Completed under emergency NTP received from KO on 12/29/23 for NTE \$1,000.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	4.5	\$ 100.00	\$ 450.00
			\$ -

Material List:

	Quantity	Cost	Total
Ceiling Tiles (2x2x5/8, 64sf)	3	\$ 63.00	\$ 189.00
Pipe Insulation (approx 70lf)	1	\$ 68.00	\$ 68.00
Miscellaneous Supplies	1	\$ 25.00	\$ 25.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$450.00	\$282.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$732.00	\$87.84	\$43.92	\$863.76