

Date: 7-31-24

Region: 4C

CSS No.: 98597

FAC ID: WV006

Maximo WO No.: 16367

Asset #:

Priority: 1



Original Work Request:

The air compressors in the AMSA are not running keep tripping breaker. Air compressors are detrimental to AMSA for work orders. Emergency can be delayed until first thing in the morning, unless Tech is close to address before 1700.

Description of Repairs Needed:

Labor to troubleshoot, diagnose and make necessary repairs to the AMSA air compressors. Found that phase monitor needs to be replaced. Will quote customer on needed repairs.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	5.1	\$ 137.00	\$ 698.70
Trip Charge	1	\$ 52.50	\$ 52.50

Material List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$751.20	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$751.20	\$90.14	\$45.07	\$886.42