

Date: 7-25-24

Region: 4C
FAC ID: WV006

CSS No.: 98599
Maximo WO No.: 16368

Asset #:

Priority: 3



Original Work Request:

The exhaust fan in the mechanical room was making a buzzing sound, so I disconnected it and it stopped buzzing, possibly needs to be replaced.

Description of Repairs Needed:

Proposal is to replace the exhaust fan motor with like model and verify operations.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	2.5	\$ 100.00	\$ 250.00
			\$ -

Material List:

	Quantity	Cost	Total
Dayton 4YU33 Motor, Sh Pole, 1/25 hp, 1550, 115V	1	\$ 120.99	\$ 120.99
shipping/handling	1	\$ 35.00	\$ 35.00
Misc (shop supplies)	1	\$ 25.00	\$ 25.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$250.00	\$180.99	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$430.99	\$51.72	\$25.86	\$508.57