

Date:

Region:

FEMS/CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



Original Work Request:

No heat call. Boilers are not providing heat because they are timing out.

Description of Repairs Needed:

Investment is to replace the combustion blower assembly on the Laars Boiler #1 (M# CB-M2-250N; S# H09212639) that serves the building heating loop.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	10	\$ 138.00	\$ 1,380.00
Trip Charge	30	\$ 1.75	\$ 52.50
			\$ -

Material List:

	Quantity	Cost	Total
JF1H094N Combustion blower	1	\$ 2,410.67	\$ 2,410.67
shipping and handling	1	\$ 195.00	\$ 195.00
Misc Parts (shop supplies)	1	\$ 72.00	\$ 72.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,432.50	\$2,677.67	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$4,110.17	\$493.22	\$246.61	\$4,850.00