

Date: 7-31-25

Region: 4C

FAC ID: WV006

FEMS/CSS No.: 3190186

Maximo WO No.: 19798

Asset #:

Priority: 1



Original Work Request:

The facility is undergoing a renovation and the AMSA employees are using the main door on the wash bay to enter/exit the building and the key is not locking the door. This is an issue because we have multiple people coming and going and they need to secure their area. Emergency contact onsite: Rick Motzer 304-654-7524

Description of Repairs Needed:

Tech inspected and discovered the exterior trim is defective. Replaced exterior trim and replaced door handle. Ensured proper operation before leaving.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	2	\$ 148.00	\$ 296.00
Travel Charge	1	\$ 148.00	\$ 148.00
			\$ -

Material List:

	Quantity	Cost	Total
Handle (PHW1001)	1	\$ 166.91	\$ 166.91
Fuel surcharge	1	\$ 59.90	\$ 59.90
shop supplies	1	\$ 29.65	\$ 29.65
freight	1	\$ 15.02	\$ 15.02
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$444.00	\$271.48	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$715.48	\$85.86	\$42.93	\$844.27