

Date: 7/5/2023



Region: 4C

CSS No.: 91935

FAC ID: WV006

Maximo WO No.: 13011

Asset #:

Priority: 2

**Original Work Request:**

Disposal in kitchen looks like the hole bottom bearings and all came apart. Needs to be replaced

**Description of Repairs Needed:**

Replace kitchen disposal and disposal controller. Rewire new controller to unit. Disposal: 208v/60/3-PH, 14.5 amps. Estimated lead time 1 week

Labor:	Labor Hrs	Labor Rate	Total
2 Techs	14	\$ 100.00	\$ 1,400.00
			\$ -

Material List:	Quantity	Cost	Total
Master disposers B5-L-Basic "B" Series Food Waste Disposer	1	\$ 5,896.00	\$ 5,896.00
Master Disposers RAC2-KP RAC2 Disposer Control Panel	1	\$ 2,198.06	\$ 2,198.06
Miscellaneous Parts and shop supplies	1	\$ 100.00	\$ 100.00
Shipping/Handling	1	\$ 306.99	\$ 306.99
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**

**Estimate Summary:**

Labor	Material	Equipment
\$1,400.00	\$8,501.05	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$9,901.05	\$1,188.13	\$594.06	\$11,683.24