

Date: 7/20/2023

Region: 4C

FAC ID: WV007

CSS No.: 92285

Maximo WO No.: 12368

Asset #:

Priority: 2



Original Work Request:

Replace loop temperature sensor and suction line sensor on the Trane chiller.

Description of Repairs Needed:

Investment is labor and material to replace the loop temperature sensor, suction line sensor, and flow monitoring on the Trane Chiller (M#CGAM080; S#U15B47125).

Labor:	Labor Hrs	Labor Rate	Total
1 Tech	8	\$ 125.00	\$ 1,000.00
Trip Charge	20	\$ 1.75	\$ 35.00

Material List:	Quantity	Cost	Total
Temperature Sensor - Trane (SEN02133)	1	\$ 158.42	\$ 158.42
Suction Line Sensor - Trane (SEN02039)	1	\$ 142.61	\$ 142.61
Flow Monitoring Kit - IFM Efactor (U440100)	1	\$ 949.45	\$ 949.45
Shipping & Handling	1	\$ 71.44	\$ 71.44
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,035.00	\$1,321.92	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,356.92	\$282.83	\$141.42	\$2,781.17