

Date: 7/6/2023

Region: 4C
FAC ID: WV007

CSS No.: 93275
Maximo WO No.: 13044

Asset #:

Priority: 3



Original Work Request:

CAC reader at the back door by loading dock is not working and needs repaired.

Description of Repairs Needed:

Diagnose and replace the nonfunctional biometric CAC Reader located at the back door by loading dock.

Labor:

	Labor Hrs	Labor Rate	Total
2 Techs	16	\$ 85.00	\$ 1,360.00
			\$ -

Material List:

	Quantity	Cost	Total
CAC Veridt Stealth Series Multimode #900W2030-WGPON	1	\$ 1,550.00	\$ 1,550.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,360.00	\$1,550.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,910.00	\$349.20	\$174.60	\$3,433.80