

Date: 11-03-23

Region: 4C
FAC ID: WV007

CSS No.: 95066
Maximo WO No.: 13990

Asset #: []

Priority: 3



Original Work Request:

The 180 degree water heater in kitchen is leaking and needs repaired or replaced

Description of Repairs Needed:

Replace compact booster heater with new 6 gallon electric heater and discard old unit. Limitations and Exclusions: Repair limited to replacing current unit and replacing with new, hooking up power and ensuring new unit is operational.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	10	\$ 100.00	\$ 1,000.00
			\$ -

Material List:

	Quantity	Cost	Total
Miscellaneous	1	\$ 75.00	\$ 75.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
Booster Heater (Hatco Model: C-12-208-3-QS)	1	\$ 2,567.00	\$ 2,567.00
Freight	1	\$ 240.00	\$ 240.00
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,000.00	\$75.00	\$2,807.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,882.00	\$465.84	\$232.92	\$4,580.76