

Date: 7-25-24

Region: 4C

CSS No.: 98180

FAC ID: WV007

Maximo WO No.: 16376

Asset #:

Priority: 3



Original Work Request:

The 2 split units for the server rooms are not cooling, these pieces were never put on PM inventory and Casto has quoted these already.

Description of Repairs Needed:

Investment is to replace the front Computer Room condensing unit. This proposal is a follow up to WO #16129 which included leak testing both the front and rear units. It was determined that the front unit needs replacing.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	10	\$ 138.00	\$ 1,380.00
Tech (1)	10	\$ 120.00	\$ 1,200.00

Material List:

	Quantity	Cost	Total
YN024GMF122RPE Condensing Unit - Pioneer Ductless	1	\$ 1,788.80	\$ 1,788.80
shipping & handling	1	\$ 227.50	\$ 227.50
Misc Parts (wiring, brackets, shop supplies, etc)	1	\$ 180.00	\$ 180.00
Trip charge	30	\$ 1.75	\$ 52.50
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$2,580.00	\$2,248.80	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$4,828.80	\$579.46	\$289.73	\$5,697.98