

Date: 6-13-25

Region: 4C

FEMS/CSS No.: 3113822

FAC ID: WV007

Maximo WO No.: 19220

Asset #:

Priority: 2



Original Work Request:

Replace stage 2 compressor on the chiller. Casto tech repaired the sensors but second stage compressor was locking up and needs replaced.

Description of Repairs Needed:

Proposal is to replace the stage 2 compressor as recommended. Includes replacing compressor, filter drier and charge Trane chiller.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	16	\$ 138.00	\$ 2,208.00
Tech (1)	16	\$ 120.00	\$ 1,920.00
Trip Charge	50	\$ 1.75	\$ 87.50

Material List:

	Quantity	Cost	Total
Compressor (COM09462)	1	\$ 8,474.88	\$ 8,474.88
Filter drier (COR00241)	1	\$ 31.66	\$ 31.66
Oil (OIL00080)	1	\$ 174.78	\$ 174.78
freight	1	\$ 455.00	\$ 455.00
R-410A refrigerant	20	\$ 19.59	\$ 391.78
Misc (tubing, clamps, fittings, shop supplies, etc.)	1	\$ 270.00	\$ 270.00
			\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$4,215.50	\$9,798.10	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$14,013.60	\$1,681.63	\$840.82	\$16,536.05