

Date: 12-22-25

Region: 4C

FEMS/CSS No.: 3156566

FAC ID: WV007

Maximo WO No.: 20931

Asset #:

Priority: 3



Original Work Request:

AHU #5 in ceiling by men restroom on second floor is in alarm and not running.

Description of Repairs Needed:

Proposal is to replace the motor in AHU #5. Motor was originally reset, but is running bad due to bearings.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	3.5	\$ 100.00	\$ 350.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Motor (DJ32P1DM)	1	\$ 433.50	\$ 433.50
freight	1	\$ 75.00	\$ 75.00
tax for motor	1	\$ 26.01	\$ 26.01
Misc (shop supplies)	1	\$ 25.00	\$ 25.00
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$350.00	\$559.51	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$909.51	\$109.14	\$54.57	\$1,073.22