

Date: 8-14-25

Region: 4C

FAC ID: WV007

FEMS/CSS No.: 3265677

Maximo WO No.: 19812

Asset #:

Priority: 2



Original Work Request:

CAC readers not working. The CAC readers are not working and has become a security issue.

Description of Repairs Needed:

Proposal is repair/replace CAC reader at the man door at back loading and the man door at the side of the building next to the steps . SOW is to replace and program to require use of PIN to enter.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	32	\$ 95.00	\$ 3,040.00
Administrative	1	\$ 100.00	\$ 100.00
			\$ -

Material List:

	Quantity	Cost	Total
DRM Board	1	\$ 548.00	\$ 548.00
Biometric Card Reader	1	\$ 3,100.00	\$ 3,100.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$3,140.00	\$3,648.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$6,788.00	\$814.56	\$407.28	\$8,009.84