

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
MOTION SENSORS

SITE AND BLDG #:WV020-01

MECHANIC SIGNATURE: *Mike Merchant* DATE: *30 Jul 19*

LOCATION/RM #:

START TIME: _____ FINISH TIME: _____

Site Location	WO #	Asset #	PM #	Manufacturer	Model Number	Serial #	Asset Description	Physical Asset Location
WV020-01	9713	6481					J-1502000-18 2-pc Motion Sensor	

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)	
		YES	NO		
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered to.			SPECIAL INSTRUCTIONS	
2	Schedule and coordinate work with operating personnel.			<i>Completed by Sub.</i>	
3	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.				
TO BE PERFORMED AT EACH INSPECTION SERVICE					
1	Check for proper functioning.			<i>See Gen</i>	
2	Inspect visual condition of motion lens.			<i>(Work performed)</i>	
3	Check for proper light operation.				
6	For any noted deficiency, takes pictures and open corrective maintenance ticket.				

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes: