

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST **MOTION SENSORS**

SITE AND BLDG #: WV020-01

MECHANIC SIGNATURE: Mike Merchan **DATE:** 12 Aug 19

LOCATION/RM #:

START TIME: 12:00 pm **FINISH TIME:** 1:00 pm

Site Location	WO #	Asset #	PM #	Manufacturer	Model Number	Serial #	Asset Description	Physical Asset Location
WV020-01	9713	6481					J-1502000-18 2-pc Motion Sensor	

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ACTIONS (IF TASK COMPLETE IS CHECKED NO. PROVIDE EXPLANATION)
		YES	NO	
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered to.	☒		
2	Schedule and coordinate work with operating personnel.	☒		
3	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.	☒		Completed. See COM
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Check for proper functioning.	☒		
2	Inspect visual condition of motion lens.	☒		
3	Check for proper light operation.	☒		
6	For any noted deficiency, takes pictures and open corrective maintenance ticket.	☒		

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.
To be performed by: General Maintenance Worker

Additional Notes: