

Date: 5-24-24

Region: 4C

CSS No.: 97661

FAC ID: WV024

Maximo WO No.: 15602

Asset #:

Priority: 3



**Original Work Request:**

The foyer unit heater, elecric wall mounted knob is broken as well as it is no longer heating. Asset #4202 located in the foyer. It needs repaired or replaced.

**Description of Repairs Needed:**

Replace motor and knob on foyer unit heater.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	3.5	\$ 100.00	\$ 350.00
			\$ -

**Material List:**

	Quantity	Cost	Total
Unit Heater Motor- 120V, 1075 RPM, 0.33HP (BOCK5488XL)	1	\$ 160.63	\$ 160.63
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**



**Estimate Summary:**

Labor	Material	Equipment
\$350.00	\$160.63	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$510.63	\$61.28	\$30.64	\$602.54