

Date: 12/11/24

Region: 4C

FEMS/CSS No.: 2966057

FAC ID: WV024

Maximo WO No.: 17376

Asset #:

Priority: 1



Original Work Request:

No heat call - Arrived on site to find the Daikin system in a UE code which is a disruption of "communication causing an error between the indoor nit and the centralized control device." Recommended contractor: Casto

Description of Repairs Needed:

Troubleshoot error code on Daikin system.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	3	\$ 138.00	\$ 414.00
Trip Charge	1	\$ 105.00	\$ 105.00
			\$ -

Material List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$519.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$519.00	\$62.28	\$31.14	\$612.42