

Date: 2-7-2025

Region: 4C

FEMS/CSS No.: 2966315

FAC ID: WV024

Maximo WO No.: 17997

Asset #:

Priority: 2



Original Work Request:

Gal HW Tank Replacement - CMI Tech, Brian discovered a leaking hot water heater in the OMS is leaking from the bottom. He turned the water supply off, placed a bucket underneath and notified on site personnel. CMI requested ticket.

Description of Repairs Needed:

Replace leaking HW heater with like model and dispose of old unit.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	7	\$ 100.00	\$ 700.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Rheem 3800-Watt Water Heater (XE20S06ST38U0)	1	\$ 450.00	\$ 450.00
Misc (copper fittings, hose, solder, shop supplies, etc.)	1	\$ 100.00	\$ 100.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$700.00	\$550.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,250.00	\$150.00	\$75.00	\$1,475.00