

**PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST**  
**MOTION SENSORS**

SITE AND BLDG #:WV029-01

MECHANIC  
 SIGNATURE: 

DATE: 2-8-15

LOCATION/RM #:

START TIME: 8:00 AM FINISH TIME: 9:00 AM

Site Location	WO #	Asset #	PM #	Manufacturer	Model Number	Serial #	Asset Description	Physical Asset Location
WV029-01	9676	6419					J-1502000-18 1-pc Motion Sensor	
WV029-01	9676	6484					J-1502000-18 2-pc Motion Sensor	

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		SPECIAL INSTRUCTIONS	NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO. PROVIDED EXPLANATION)		
		YES	NO				
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered to.	X					
2	Schedule and coordinate work with operating personnel.	X					
3	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.	X					
TO BE PERFORMED AT EACH INSPECTION SERVICE							
1	Check for proper functioning.	X					
2	Inspect visual condition of motion lens.	X					
3	Check for proper light operation.	X					
6	For any noted deficiency, takes pictures and open corrective maintenance ticket.	X					

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found

exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

**Additional Notes:**