

Date:

Region:
FAC ID:

CSS No.:
Maximo WO No.:

Asset #:

Priority:



Original Work Request:

To provide and install (1) new system sensor outdoor speaker-only device, found to be water damaged and non-functional

Description of Repairs Needed:

Provide and install (1) new system sensor outdoor speaker-only device, found to be water-damaged and non-functional on recent service request. Exclusions: replacement of existing defective materials other than as listed in the above scope of work, upgrade to existing system or components, if cell communicator not sufficient in the area of the panel, an external antenna may have to be added at additional cost.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	8	\$ 131.25	\$ 1,050.00
			\$ -

Material List:

	Quantity	Cost	Total
System Sensor (model SPWK)	1	\$ 212.50	\$ 212.50
miscellaneous	1	\$ 75.00	\$ 75.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,050.00	\$287.50	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,337.50	\$160.50	\$80.25	\$1,578.25