

Date: 8-28-24

Region: 4C

CSS No.: 98267

FAC ID: WV035

Maximo WO No.: 16401

Asset #: []

Priority: 2



Original Work Request:

Two exhaust fans were found to have bad motors (Assets #s 3912 and 3506)

Description of Repairs Needed:

Replace motors in exhaust fans identified as bad during June PMs. Quote includes the use of a lift.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	6	\$ 100.00	\$ 600.00
			\$ -

Material List:

	Quantity	Cost	Total
Motors (Modine, PN-9F0101260000) *only 2 in stock	2	\$ 281.46	\$ 562.92
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
Scissor Lift	1	\$ 945.00	\$ 945.00
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$600.00	\$562.92	\$945.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,107.92	\$252.95	\$126.48	\$2,487.35