

Date: 12-18-25

Region: 4C

FAC ID: 3432910

FEMS/CSS No.: 3432910

Maximo WO No.: 20926

Asset #:

Priority: 1



**Original Work Request:**

No Heat, multiple boiler issues

**Description of Repairs Needed:**

Per contractor Service Report, the fuel pump needs replacing. A separate WO is generated for this additional repair. See attached Service Report.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	8	\$ 142.00	\$ 1,136.00
Travel Time	2	\$ 142.00	\$ 284.00
Tech (1)	8	\$ 120.00	\$ 960.00
Travel Time	2	\$ 120.00	\$ 240.00
Trip Charge	90	\$ 1.75	\$ 157.50

**Material List:**

	Quantity	Cost	Total
Oil pump (BCCR3-OBO	1	\$ 2,145.21	\$ 2,145.21
Freight	1	\$ 97.50	\$ 97.50
Misc (shop supplies)	1	\$ 72.00	\$ 72.00
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**



**Estimate Summary:**

Labor	Material	Equipment
\$2,777.50	\$2,314.71	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$5,092.21	\$611.07	\$305.53	\$6,008.81