

## Additional Funding Request

Submitted: 3/14/2019

<b>MD013</b> – water analysis <b>MD021</b> – water analysis <b>VA002</b> – water analysis <b>MD066</b> – water analysis	<b>CSS #18207 WO#8252</b>
Description of Repairs	Initial water analysis, documentation and recommendation for closed loop water systems performed by Bond Water Technologies.
Original SC Investigative Diagnosis	<b>\$600.00</b>  \$150 for each site visit at MD013, MD021, VA002, MD066 Zone 1, Region 5
Diagnosis: Initial Work Order	Site visits for boiler corrosion inhibitor costs.
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	<b>Materials: = NA</b>
Additional Labor Cost to Perform Repairs	<b>Labor: NA</b>
<b>Total Cost of Repair</b>	<b>\$600.00</b>