



INVOICE

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd.
Alexandria, VA. 22312

April 8, 2020

RE: Saug NY128 css228565 WO
6489
DOMESTIC HOTWATER TANK #1
IS LEAKING AT WATER FEED
LINE

- Isolate compromised fitting.
- Remove fitting (s) as necessary and replace.
- Remove and re-install existing pipe insulation.
- check for leaks.

1 Misc copper fittings and solder

Total Due 1212.00

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email rdpostulka@verizon.net

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL