



# INVOICE

CMI Management  
Mr. Steve Miller  
5285 Shawnee Rd.  
Alexandria, VA. 22312

Sep 2, 2019

RE:  
CSS19946 New Windsor USAR Doorway overhang soffits at three entry points  
to  
the training building need to be replaced due to high wind and water damage.  
The areas are the training building rear entry, kitchen entry and the main  
entry point. The main entry point has a leak in the roof causing continuing  
water damage. Urgent

- Remove existing overhang soffitt panels at all three entry points.

- Install 2x6 structural rough framing and furring strips.

- Install perimeter trim cap

- Install new soffit panels to match existing.

- Remove and re-install existing light fixtures

- Repair flashing leak on front roof

-	(62)pcs. vinyl soffit.	9.99.	619.38
	(15) pcs Channel cap	4.88.	73.20
	(20) 2x6x16ft. Home Depot	12.52	252.40
	Misc hardware & calk.		50.00
			-----
			994.98
	Tax 7%.		69.65
			-----
			1064.63
	20%		212.93.
			-----
			1277.56
	Labor 130 hrs @120.00		15600.00
			-----
			16877.56

701 Randall Rd Ballston Spa, NY 12020      TEL 518-441-6003 FAX 518-399-5440

Email [rdpostulka@verizon.net](mailto:rdpostulka@verizon.net)

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL



INDUSTRIAL

COMMERCIAL

INSTITUTIONAL