

Richard Hicks

From: Richard Hicks
Sent: Monday, March 7, 2022 4:38 PM
To: Augustin, Kenneth P CIV USARMY 99 RD (USA); donald.l.huson.ctr@army.mil; Mary Lowery; Adam Colopy; Tina Lee
Cc: Devlin, Thomas J CIV USARMY CENAP (US)
Subject: VA099 WO# 16752 CSS# 34571 UPDATES

Ken , Don , Team ,

Maximo notes : 3/7-Moore's onsite today -Moore's tech called Rick 4pm Monday - Moore's Reported they tested cleaned fan control relays and were able to get fan operational - Moore's recommended -any work related to this Kitchen fan / Ansul fire suppression system to get looked at by a fire protection company like Simplex. Ken this needs to be done by your CC going forward ..We can discuss during our call tomorrow .

Work Order	Description	Site	Location / Fac. ID
16752	KEF-1 Kitchen Exhaust Fan contactor does not stay closed to operate the fan	99REG5	VA099-01

3/7- work completed pending uploads

Thanks,
Rick

Rick Hicks
PM / 99TH -Region 5
5285 Shawnee Road
Suite #510
Alexandria , VA 22312
703-738-5301
Richard.Hicks@cmimgmt.com