



Date: 4/30/2021
Service Order: 21-0006142

Order Status: Complete

Customer	Problem
US ARMY RESERVE #NY054 -CMI MGMT US ARMY RESERVE #NY054 -CMI MG 5363 PERU STREET PLATTSBURGH NY Who called: VANESSA FERNAND	<p>**SCHEDULED FOR 4/30 WITH RON VOYT (315.772.8801)** PAUL // PART REC'D 4/27 -BRANDI</p> <p>***PART ON ORDER 4/21 -Brandi</p> <p>Quoted \$719.28 on 624, approved 4/21 -Brandi</p> <p>PO#12844/NTE\$450.00/CSS#30081 NY054 Plattsburg USARC, EMERGENCY LIGHT IN SUPPLY BUILDING BUZZING</p> <p>4/19/2021 pw US Army reserve - report of emergency light buzzing, inspected and found transformer to be bad. New emergency light needed. Model number emcua00074 Work order not complete</p>

Work Performed
4/30/2021 pw US Army Reserve Quoted work to replace faulty emergency light - Checked in with Sgt Griffin. Removed power from light. Unwired and removed unit. Prepared new unit for installation. Mounted new unit on same wall location. Wired unit in and connected battery. Reapplied power and verified operation of unit Work order complete

Tech Name	Reg. time	Overtime	Dbl. time
Paul Williams	2:00	0:00	0:00

Signature: C19 - Sgt Griffin