

## Additional Funding Request

<b>NY126– Dishwasher</b>	<b>Maximo WO # 6845 CSS# 16695 Asset # 3164</b>
Description of Repairs	Labor and materials to repair the Hobart Dishwasher.
Diagnosis: Initial Work Order	Make repairs to oven and dishwasher at facility. Oven- Bottom oven is not heating up. Dishwasher is not working. I have checked electrical box to confirm that the breaker has not been tripped. The 490th has cooks assigned as part of their MTOE, and use it most BA weekends.
Explanation of Additional Costs for Repairs	Labor and material repair the dishwasher.
Investigative Diagnosis from SC	\$234.00 (\$92.00 x 2 = \$184.00 Travel Charge (\$50.00)
Additional Material Cost to Perform Repairs	Solenoid Valve (Qty 1) \$252.39 Vacuum Breaker Service Kit (Qty 1) \$45.93 O"" Ring (min. of 6) (Qty 1) \$4.28 Gasket (Qty 1) \$3.84 Rinse Arm Plug (Qty 1) \$13.24 3/4 Pressure Regulator (Qty 1) \$85.00 Pressure/Temperature Relief Valve (Qty 1) \$106.00 Liquid Tech (Qty 1) \$38.50 Shipping and Handling \$45.00
Additional Labor Cost to Perform Repairs	Comm Service Labor \$92 an hour x 6 hours \$552.00
Total Cost of Repair	\$1380.18





