

Additional Funding Request

Site: WV002	WO# 5182 CSS # 14500 Asset# NA
Description of Repairs	Repair Exhaust Fan in OMS Latrine
Diagnosis: Initial Work Order CSS# 14500	Repair Exhaust Fan in OMS Latrine
Explanation of Additional Costs for Repairs	Labor and material to replace broken exhaust fan in the OMS Latrine
Additional Labor Cost to Perform Repairs	8x\$115.00=\$920.00
Additional Material Cost to Perform Repairs	\$581.00
Total Cost of Repair	\$1,501.00

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: WV002

Date of Visit: 8/3/18

Contractor Personnel on Site:

1. Casto Tech

2. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# 151013, 152459

Service Calls - Service Call Number and Description

1. CSS# CSS# 14542

2. CSS# CSS# 14500

3. CSS# _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Shawn V. Shelton Date: 8/3/18

Signed: Shawn V. Shelton

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Benitez, Joel / SPC Date: 08/03/18

Signed: _____

E-Mail: Joel.Benitez.mil@mail.mil



QUOTE

Client Name: USARC - Beaver WV002

Contact: Darrell Lucas

Date: 08/06/2018

Quote Number: 152591

Location: USARC - Beaver WV002

201 Industrial Park Road

Cornelius Charlton USARC

Beaver, WV 25813

PO Box 627
540 Leon Sullivan Way
Charleston, WV 25301
Charlie Cook
304-346-0549x1252
304-346-8920 Fax
service@castotech.com

Description	Quantity	Price	Line Total
VQ0200 Exhaust Fan, Stephany Assoc	1.00	\$456.00	\$456.00
Shipping & Handling	1.00	\$65.00	\$65.00
Onsite Labor	8.00	\$115.00	\$920.00
Trip Charge	20.00	\$1.75	\$35.00
Service Supply Charge	1.00	\$25.00	\$25.00
Subtotal:			\$1,501.00
Estimated Sales Tax:			\$0.00
Total:			\$1,501.00

Investment is labor and materials to replace the exhaust fan in the Motor Pool at USARC Beaver, WV002, CSS#14500.

This is a quotation on the goods named and further subject to the standard terms and conditions attached hereto.

Acceptance of quotation

Authorized Representative

Purchase Order #

☐ Warranty Option – For an additional \$75.05, I'd like to extend the labor warranty to 12 months.

EXCLUSIONS:

1. All asbestos testing and removal will be owner's responsibility
2. All roof work

CLARIFICATIONS:

1. The price of a performance/payment bond is not included.
2. The cost of permits and inspections by outside authorities are not included.
3. Work will be performed during normal business hours (**Monday-Friday, 8:00 a.m.-4:30 p.m.**).
4. Our terms are net thirty days.
5. Price held firm for 60 days.
6. Standard Warranty - 1 Year Parts and Labor.

***Thank you for your
business!***

Charlie Cook

From: Charlie Quick
Sent: Monday, August 6, 2018 10:18 AM
To: Charlie Cook
Cc: Shawn Shelton
Subject: USARC Beaver

1	VQ0200	Exhaust Fan	\$380.00
---	--------	-------------	----------

Vendor- Stephany Associates/ Jamie

Charlie Quick /Purchasing
Casto Technical Services
1428 Pennsylvania Avenue, Charleston, WV 25302
Email Cquick@castotech.com
Office phone 1-304-346-0549



DO NOT REMOVE THIS LABEL
NOT FOR USE IN KITCHENS.
To protect finish, wash with mild soap or detergent only.

MODEL NO.	VOLTS	HZ	AMPS	WATTS
V200	120	60	1.3	115

LIFETIME LUBRICATED.

MASTER-ETTE
ACME ENGINEERING & MANUFACTURING CORP.
P.O. BOX 576
MURKOGEE, OKLAHOMA

UL LISTED FANS 969G E-1014 99073602A