



Asset# 4533. Hot water unit heater located in mechanical room is leaking water from the union connection. Request is for vendor to repair leak and verify heater is fully operational.

Proposal to remove and replace old Die Electric Union with a new Die Electric Union.