



During my check of the generator at this building I found the control panel to be "dark". I contacted Cummins and they helped me troubleshoot and determined that battery and battery charger were "dead". Generator is in-operable until these repairs are made. Generator serves emergency lighting and heating system.

Unit requires a new battery & charger to ensure reliable operation.

CMI Cost Estimate								
Funding Request								
PA051-194 Johnstown								
During my check of the generator								
CSS #14723 - CMI # 5902								
Prepared By: J. Bayne								
1.03.19								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 145.00	2.7						\$ 391.50
1.2 Battery Charger / material					\$ -	\$ -	\$ -	\$ 445.08
1.3 Misc.								\$428.60
1.4 Travel								\$ 290.00
2 hours travel								
Sub Total Repair Cost								\$ 1,555.18
2.1 Total Tax								\$ 32.02
Grand Total								\$ 1,587.20