

Additional Funding Request

PA168 – Ice Machine	Maximo WO # 6449 CSS# 14473 Asset #6845
Description of Repairs	Labor and materials to install new ice machine. Includes technician, and helper, and limited installation material, to re-connect to existing drain, and water lines.
Diagnosis: Initial Work Order	Ice machine located in training room kitchen is inoperable. Request is for vendor to troubleshoot and make necessary repairs.
Additional Material Cost to Perform Repairs	Misc installation material \$ 150.00
Diagnostic Fee	\$450.00
Additional Labor Cost to Perform Repairs	6 hrs X \$120 an hour (1 technician) (\$720.00) Travel charge \$1.00/ mile @32 miles \$ 64.00
Total Cost of Repair	\$1384.00