

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MD006

Date of Visit: 6/4/19

Contractor Personnel on Site:

1. Tony Lazarus
2. Jim Geertjes
3. Scott Berry

4. _____
5. _____
6. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

- | | | |
|----|-------------|-------------|
| 1. | <u>9131</u> | <u>9332</u> |
| 2. | <u>9256</u> | <u>9444</u> |
| 3. | <u>9296</u> | <u>9378</u> |
| 4. | <u>9374</u> | |

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Jim Geertjes

Date: 6-4-19

Signed: [Signature]

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Jesse Schultz ARA Date: 6/4/19

Signed: [Signature]

OTHER RECURRING SERVICES CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MD006

Date of Visit: 6/4/19

Contractor Personnel on Site:

1. Tony Lozano

2. Jon Gerdner

3. Scott Werry

4. _____

5. _____

6. _____

Work Performed:

Other Recurring Services

1. 9224

2. _____

3. _____

4. _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Jon Gerdner

Date: 6-4-19

Signed: _____

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Jesse Schmitz ARA

Date: 6/4/19

Signed: _____

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST GREASE TRAP

SITE AND BLDG #: MD 006 -G1
LOCATION/RM #: Kitchen WO# 9286 ASSET # 7477

MECHANIC
SIGNATURE: 

DATE: 6/4/19

START TIME: 1000

FINISH TIME: 1010

ITEM NO.	CHECK POINT DESCRIPTION	TASK COMPLETE		REMARKS/NOTES
		YES	NO	
SPECIAL INSTRUCTIONS				
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered.			
2	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.			
3	Insure proper grease disposal.			
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Do not use enzymes, acids, caustics, solvents or emulsifying products when cleaning or maintaining the grease traps.			
2	Remove lid. If the trap is equipped with removable baffles, remove them.			
3	Make sure the flow restrictor on the inflow pipe is present.			
4	If damages, missing parts, or cleaning is required, report them as needed to ensure proper working operation.			
5	Replace lid and baffles.			
6	Return (or fill) water to grease trap			
7	Record grease trap maintenance activities on your log or request a receipt from your grease hauler. Keep records for 3 years.			

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed discription of the deficiency.
To be performed by: General Maintenance Technician

Additional Notes: