

OTHER RECURRING SERVICES CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FacID/Building: P-051-07 Date of Visit: 6/12/19

Contractor Personnel on Site:

Scott Werry

2.

3.

4.

5.

6.

Work Performed:

Other Recurring Services

1.

9210

2.

3.

4.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Scott Werry

Date: 6/12/19

Signed: Scott Werry

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Knight, Eric SGT

Date: 2019 06 12

Signed: JK

E-Mail:

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
LIGHTING, OUTSIDE

SITE AND BLDG #: *Pr 051 -07*LOCATION/RM #: *MEP* WO# *9216*ASSET # *7426*MECHANIC
SIGNATURE: *Scott Murphy*DATE: *6/2/18*

START TIME:

FINISH TIME:

ITEM #	DESCRIPTION	TASK COMPLETION		NOTES/REMARKS
		YES	NO	
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered to.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
2	Schedule and coordinate work with operating personnel.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
3	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Open and tag switch.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
2	Inspect visual condition of wiring. Look for evidence of overheating.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
3	Check for proper light operation.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
4	Test operation of automatic switches/ time clock/ photocells if applicable.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
5	Inspect light pole and mounting devices for deficiencies.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
6	For any noted deficiency, takes pictures and open corrective maintenance ticket.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes:

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
GATES, FENCES, SECURITY AND ACCESS

SITE AND BLDG #:

P-071 -07

MECHANIC
SIGNATURE:

DATE:

8/12/13

LOCATION/RM #:

M-01

WO# 9216

ASSET # 7558

START TIME:

9:40

FINISH TIME:

9:55

ITEM	CHECKPOINT DESCRIPTION	TASK COMPLETED YES <input type="checkbox"/> NO <input type="checkbox"/>	NOTES/ACTIONS	
			AFTER COMPLETED/INSPECTED & APPROVED/VALIDATION	
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered.	<input checked="" type="checkbox"/>		
2	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.	<input checked="" type="checkbox"/>		
TO BE PERFORMED AT EACH INSPECTION SERVICE				
GATES				
1	Inspect all pivot points, hinges, latches, etc. Apply lubricant where needed, wiping off excess.	<input checked="" type="checkbox"/>		
2	Check all locking devices. Lubricate as required.	<input checked="" type="checkbox"/>		
3	Inspect center gate support rollers and lubricate as required.	<input checked="" type="checkbox"/>		
4	Clean roller track of any debris.	<input checked="" type="checkbox"/>		
5	Check bolts, fasteners, and mounting hardware. Tighten or adjust as necessary.	<input checked="" type="checkbox"/>		
6	Check for any obstructions that retard full swing or movement of the gate.	<input checked="" type="checkbox"/>		
7	Check that shrubs and trees are pruned clear of gate.	<input checked="" type="checkbox"/>		
8	Check hold open devices for proper operation. Lubricate as required.	<input checked="" type="checkbox"/>		
FENCES				
1	Check posts and corner posts, support guys, and horizontal bars between each support post.			
2	Check wire and anchor point; re-stretch and re-anchor if necessary.			
3	Inspect fence anchors along the bottom of the fence and at the point where the fence is connected to the post.			
4	Treat with galvanized protectant where rust has developed.			
5	If approved, apply weed control along entire base of fence. Consult the Safety Data Sheets (SDS) for hazardous ingredients and proper personal protective equipment (PPE).			
6	Check that shrubs and trees are pruned clear of fencing			

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes: