

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: Pr 067

Date of Visit: 6/20/19

Contractor Personnel on Site:

1. Tony Georges
2. Jim Beertjer
3. Scott Warr

- 4.
- 5.
- 6.

Work Performed:


Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. 9127
2. 9386
3. 9335
4. 8443

CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Jim Georges Date: 6-20-19

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: 3500.02381 Date: 20 Jun 19

Signed: 

E-Mail:

OTHER RECURRING SERVICES CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FacID/Building: Pro67 Date of Visit: 8/20/19

Contractor Personnel on Site:

1. Tony Geraas
2. Jim Geertges
3. Scott Werry
4. _____
5. _____
6. _____


Work Performed:

Other Recurring Services

1. 9209
2. _____
3. _____
4. _____


CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Jim Geertges Date: 6-20-19
Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: SSgt Jrg R Date: 20 Jun 19
Signed: 

E-Mail:

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
EXHAUST FANS

SITE AND BLDG #: PR 062-01

LOCATION/RM #: Boiler Rm 9127 WO# 9127 ASSET # 3856

MECHANIC
SIGNATURE:

START TIME:



DATE:

6/2/11

FINISH TIME: 810

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
1	In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered to.			
2	Schedule shutdown with operating personnel, as needed.			
3	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.			
1	Clean unit, especially fan blades.	/		
2	Inspect pulleys, belts, couplings, etc.; adjust tension and tighten mountings as necessary. Change badly worn belts. Multiple belts should be replaced with matched sets.	/		
3	Perform required lubrication and remove old or excess lubricant.	/		
4	Clean motor with vacuum or low pressure dry air (less than 40 psig). Check for obstructions in motor cooling and air flow.	/		
5	Check structural members, vibration eliminators, and flexible connections. Check fan housing to ensure there is no damage and the housing is tight.	/		
6	Start unit and check for vibration and noise.	/		
7	Remove all trash and debris.	/		

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes:

EF - 1

BL

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
EXHAUST FANS

SITE AND BLDG #: *Pr 067 ~*LOCATION/RM #: *Prce* WO# *8127* ASSET # *3626*MECHANIC
SIGNATURE:

DATE:

START TIME:

FINISH TIME:

J. L. Johnson *6/26/19*

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	

- 1 In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered to.
- 2 Schedule shutdown with operating personnel, as needed.
- 3 Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.

- 1 Clean unit, especially fan blades.
- 2 Inspect pulleys, belts, couplings, etc.; adjust tension and tighten mountings as necessary. Change badly worn belts. Multiple belts should be replaced with matched sets.
- 3 Perform required lubrication and remove old or excess lubricant.
- 4 Clean motor with vacuum or low pressure dry air (less than 40 psig). Check for obstructions in motor cooling and air flow.
- 5 Check structural members, vibration eliminators, and flexible connections. Check fan housing to ensure there is no damage and the housing is tight.
- 6 Start unit and check for vibration and noise.
- 7 Remove all trash and debris.

NP
NA

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes:

EF - 1

No Power to Unit

BC