

CERTIFICATION OF WORK  
SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID Building: <sup>WV029</sup> MORGANTOWN WV Date of Visit: 5-30-25

Contractor Personnel on Site:

- |                         |          |
|-------------------------|----------|
| 1. <u>Keith Pearson</u> | 4. _____ |
| 2. <u>Wyatt Rose</u>    | 5. _____ |
| 3. _____                | 6. _____ |

Service Call Number

FEMS 3031136

WO 18471

CSS# 301136 WO# 2637

Description of Repairs

Found loop wire cut to Gate operator, pulled new wire. Now normal  
Found entire Rack Dead due to bad UPS need Replacement  
Found Basement monitor dead. Need New monitor.  
Quote - Need 2 men 1 day, 1 momentary Contact button, misc. wire,  
AND Hardware.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Keith Pearson Date: 5-30-25

Signed: [Signature]

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Erick Galkowski / SFC Date: 5-30-25

Signed: [Signature]

E-Mail: erick.w.galkowski.mil@army.mil





ALLERS!  
09-33  
USA  
OUTD  
60°C  
16  
CONDUIT  
ALLIG  
A (F)  
SOUTH

Made in Mexico  
1393









