

CSS 16121

ATTACHMENT J-0200000-05
FORMS

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PAOSI-227

Date of Visit: 1-22-19

Contractor Personnel on Site:

1. Ray Chain
2. _____
3. _____
4. _____
5. _____
6. _____

Work Performed: Replace Panel & Probe Fuses

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. _____
2. _____
3. _____
4. _____

Inspection, Testing, and Certification

1. _____
2. _____
3. _____
4. _____

Other Recurring Services

1. _____
2. _____
3. _____
4. _____

Service Calls - Service Call Number and Description

1. CSS 16121, PAOSI-227 WO 7176
2. Replace monitoring Panel
3. Replace High air Probe

**ATTACHMENT J-0200000-05
FORMS**

Over and Above Repair Work – Order Number and Description of Work Completed

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Ray chain Date: 1-22-18

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: _____ Date: _____

Signed:

E-Mail: info@mathworks.de



