

Additional Funding Request

MD005	CSS# 16319 WO# 6462 Asset# NA				
Description of Repairs	Labor and materials to replace steel man door. Door is beyond repair.				
Diagnosis: Initial Work Order	The man door at the end of the drill hall is not functioning properly. The door closer is not attached either. Needs to be repaired in order to secured the building POC is SSG Wilson at 314-853-7074 or SSG Adams at 305-890-3976				
Diagnostic Costs	\$ 0				
Additional Labor Cost to Perform Repairs	\$ 640 Labor (1) Technician \$80/Hr x 8				
Additional Material Cost to Perform Repairs	\$ 1090.15				
	Slab Only 43.5 x 79.5 Steel Door (includes closer)	1	\$1,038.24		\$1,038.24
	Sales Tax				\$51.91
Total Cost of Repair	\$ 1730.15				



WORK ESTIMATE

CSS #: 16319

Work Order #: 6462

Emergency ☐

Urgent ☐

Routine ☒

Company Name:	Tidewater, Inc.	Facility ID:	MD005
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	Exterior Door
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace steel man door. Door is beyond repair.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			8	\$640.00
Slab Only 43.5 x 79.5 Steel Door (includes closer)	1	\$1,038.24		\$1,038.24
Sales Tax				\$51.91
SUB-TOTAL COSTS:		Materials Total	\$1,090.15	Labor \$640.00
TOTAL			\$1,730.15	



The Home Depot Special Order Quote

Customer Agreement #: H2501-90955

Printed Date: 11/15/2018

Customer: JOHNNY BROWN

Address: 740 TRENTON AVE
SEVERNA PARK, MD
21146

Phone 1: 410-562-1511

Phone 2: 410-562-1511

Email: JOHNNYBROW@GMAIL.COM

Store: 2501

Associate: ROBERTA

Address: 601 NEW ORDNANCE RD
GLEN BURNIE, MD 21060


Phone: 410-553-9600

Pre-Savings Total: \$865.20

Total Savings: (\$0.00)

Pre-Tax Price: \$865.20

All prices are subject to change. Customer is responsible for verifying product selections. The Home Depot will not accept returns for the below products.



Catalog Version 37



Call Width = Custom
Call Height = Custom

Line Number	Item Summary	Was Price	Now Price	Quantity	Total Savings	Total Price
100-1	Slab Only 43.5 x 79.5 Material Type = Steel Door Layout = Flush Handing/Swing = Left Hand Outswing	\$865.20	\$865.20	1	\$0.00	\$865.20
Unit 100 Total:		\$865.20	\$865.20		\$0.00	\$865.20

Begin Line 100 Description

--- Line 100-1 ---

Steel Doors Slab Only 43.5 x 79.5
Call Width = Custom
Call Height = Custom
Handing/Swing = Left Hand Outswing
Fire Rating = 20 Minute
Material Type = Steel
Door Thickness = 1 3/4"
Door Style = Flush
Door Layout = Flush
Glass = No Glass
Door Material Thickness = Standard (20 Gauge)
Door Core = Honeycomb Core
Door Edge Construction = Lockseam
Door Cap = None

Measurements Taken From = Door
Hinge Prep = 4 1/2"
Hinge Type = Ball Bearing
Number of Hinge Cutouts = 3
Top of First Hinge = 4.5
Top of Second Hinge = 36
Top of Third Hinge = 68
Hinge Finish = Prime Coat Finish (USP)
Hinge Factory Installed = No
Door Closer = Heavy Duty
Locking Device = None
Type of Lock Prep = Horizontal Exit Device
Center Line of Strike Plate = 40
Exit Device Trim Prep = None (Exit Only)

Kickplate = No
Peep Viewer = None
Magazine Slot = None
Saddle / Threshold Depth = None
Door Bottom Gasketing = None
Weather Stripping = None
Door Stop = None
Hardware Finish = Satin Chrome (US26D)
SKU = 113776
Vendor Name = S/O L.I.F INDUSTRIES, INC.
Vendor Number = 60014403
Customer Service = 1-516-390-6800
Catalog Version Date = 1/6/2017

End Line 100 Description



PLEASE
EXTINGUISH
BEFORE
ENTERING