

Additional Funding Request

DE007	CSS# 16330 WO# 6465 Asset# 1732
Description of Repairs	Charge to investigate Boiler #2.
Diagnosis: Initial Work Order	Boiler #2 would not lite off for proving of safety devices.
Diagnostic Fee	\$0
Additional Labor Cost to Perform Repairs	\$ 650.00
PM Credit	-\$250.00
Total Cost of Repair	\$ 400.00



S&S Mechanical

Location: Newark AFRC

1001 Ogletown Road

Newark, DE 19711

Proposal Submitted to: Adam Colopy

Project: 6465

Office # 301-574-1555

Fax # 301-574-1558

seth@sandsmidatlantic.com

sandsmidatlantic.com

S&S proposes to come out to investigate boiler #2:

- “Boiler#2 would not lite off for proving of safety devices.”

Total to investigate: \$650.00

Payments to be made as follows: 15 days upon approved invoice

Respectfully submitted: Brian Davis/Molly King

Dated: 02/08/19