

Additional Funding Request

Submitted: 07/25/2022

VA701	CSS 1768 WO 18685								
Description of Repairs	Labor and materials to refill glycol tank with 35 gallons of glycol.								
Original SC Investigative Diagnosis	\$0								
Diagnosis: Initial Work Order	35 GALLONS OF GLYCOL NEEDED PROPOSAL Glycol Tank filling Maintain by refiling the glycol tank that was emptied on CSS 35331								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p>Materials: \$ 1658</p> <table border="1"> <thead> <tr> <th>ITEM</th><th>QUANTITY</th><th>UNIT PRICE</th><th>TOTAL</th></tr> </thead> <tbody> <tr> <td>Materials (See attached detail)</td><td>1</td><td>1658</td><td>1658</td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Materials (See attached detail)	1	1658	1658
ITEM	QUANTITY	UNIT PRICE	TOTAL						
Materials (See attached detail)	1	1658	1658						
Additional Labor Cost to Perform Repairs	<p>Labor: \$145</p> <p>Bond Consulting Fee \$100 Bond Environmental Fee \$45</p>								
Total Cost of Repair	\$1803								



QUOTATION

TO: CMI Management VA-701 886 Carolina Rd. Suffolk, VA	DATE OF QUOTATION:							
	7/25/22							
	Terms:			Net 30 Days				
	F.O.B.			Gaithersburg, MD				
	Delivery:							
RE: 40% Inhibited Propylene Glycol Solution mixed with De-ionized Water								
Quantity	Description	Price	Unit	Amount				
7 x 5 gal	Intercool P-300 40% Propylene Glycol	\$1,015.00	20% Markup	\$1,218.00				
	Chemical Freight and Delivery Fee	\$250.00		\$250.00				
	Handling Fee	\$190.00		\$190.00				
	Chemistry Solution Consulting Fee	\$100.00		\$100.00				
	Environmental and Regulatory Fee	\$45.00		\$45.00				
Customer Authorization to Purchase Items:		Total Amount of Quotation: Pricing does not include tax.		\$1,803.00				

PLEASE DIRECT INQUIRIES REGARDING THIS QUOTATION
to: Jon Miller at (301) 580-9820

BY: Jon Miller, CWT