

Additional Funding Request

NY126	CSS# 17769 WO# 8152 Asset# 7576			
Description of Repairs	Labor and materials to repair gate rollers on manual drive through gate.			
Diagnosis: Initial Work Order	Make repairs to gate rollers on manual drive through gate. Rollers are in disrepair and cause gate to come off track. Routine request.			
Diagnostic Fee	\$ 160.00 TW Labor \$80/hr x 2			
Additional Labor Cost to Perform Repairs	\$ 320 TW Labor \$80/hr x 4			
Additional Material Cost to Perform Repairs	\$413.10			
	2-4" Nylon Cantilever Rollers	2	\$194.40	\$388.80
	Sales Tax			\$24.30
Total Cost of Repair	\$ 893.10			



WORK ESTIMATE

CSS #: Work Order #:
Emergency Urgent Routine

Company Name:	Tidewater, Inc.	Facility ID:	NY126
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to repair gate rollers on manual drive through gate.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			4	\$320.00
2-4" Nylon Cantilever Rollers	2	\$194.40		\$388.80
Sales Tax				\$24.30
Diagnostic			2	\$160.00
SUB-TOTAL COSTS:		Materials Total	\$413.10	Labor
				\$480.00
TOTAL			\$893.10	



February 27, 2019

Patrick A. Brown

Re: Material Quote

2 – 4" Nylon Cantilever Rollers **\$ 162.00 / Each = \$ 324.00 + TAX**

NOTES:

- 1) Quote is valid for ten (10) days.
- 2) Price does not include delivery.

If you have any questions, please do not hesitate to contact me at (315) 635-0098.

Sincerely,

ARROW FENCE COMPANY, INC.

ACCEPTED BY:

Jim Potter
Commercial Sales

Signature

Print Name & Title

Date

JP: dy



