

Additional Funding Request

VA048	CSS# 21688 WO# 12615 Asset# NA											
Description of Repairs	LoCurrent tried to diagnose over the phone with Maj Drakes...unsuccessful. It appears to be Galaxy 635 CPU Board and Galaxy DRM board that need replacement. LoCurrent will diagnose and determine if that is the case.											
Diagnosis: Initial Work Order	Main gate, OMS gate and OMS CAC reader not working. We had severe thunderstorms yesterday											
Diagnostic Fee	\$ 0.00											
Additional Labor Cost to Perform Repairs	<p>\$ 1250</p> <p>Labor \$75/hr x 16</p> <p>Admin Charge \$50</p>											
Additional Cost	<p>\$ 1,041</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Galaxy CPU Board</td> <td style="width: 15%;">1</td> <td style="width: 20%;">\$495.00</td> <td style="width: 25%;">\$495.00</td> </tr> <tr> <td>Galaxy DRM Board</td> <td>1</td> <td>\$546.00</td> <td>546.00</td> </tr> </table>				Galaxy CPU Board	1	\$495.00	\$495.00	Galaxy DRM Board	1	\$546.00	546.00
Galaxy CPU Board	1	\$495.00	\$495.00									
Galaxy DRM Board	1	\$546.00	546.00									
Total Cost of Repair	\$ 2,291.00											

LoCurrent Systems, LLC

3522 County Highway 11
 Cooperstown, NY 13326
 (607)293-7300
 locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
 6625- A Selnick Drive
 Elkridge, MD 21075

ESTIMATE # 1636**DATE** 08/18/2020**P.O. NUMBER**

Emerg. call- Montieth VA048 Sys

	ACTIVITY	QTY	AMOUNT
08/18/2020	Services CSS#21688 WO#12615 Emergency Service VA048 Montieth Facility Richmond, VA USARC Diagnose System issue & repair if possible	1	2,291.00

Dear Ms. Lee:

As per your request and our Telephone conversation with Facility Personnel LoCurrent Systems is pleased to provide a quotation to diagnose System issues being experienced at the Monteith Facility Richmond, VA VA048.

As per Telephone Diagnostic with Facility Personnel it appears Galaxy 635 CPU Board and Galaxy DRM Board need replacement.

LoCurrent to arrive on site, Perform in-person Diagnostic, repair if possible or provide quotation for necessary repairs.

Cost Breakdown:

(1) Galaxy CPU	
Board.....	\$495.00
(1) Galaxy DRM	
Board.....	\$546.00
Labor (2) men 8 hours @	
\$75.....	\$1,200.00
Administrative.....	\$50.00
 Grand	
Total.....	\$2,291.00

ACTIVITY	QTY	AMOUNT
The cost for the above mentioned is not to exceed \$2,291.00		
If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed.		
Thank you so much for thinking of LoCurrent Systems.		
Sincerely,		
Antonietta LoRusso		
	TOTAL	\$2,291.00

Accepted By

Accepted Date