

Additional Funding Request

MD002	CSS# 21691 WO# 11410 Asset# NA										
Description of Repairs	Labor and material to replace exterior main entry door. Door is in bad shape replacement is recommended.										
Diagnosis: Initial Work Order	Repair exterior main entry door alignment/closure, and rm 111 door catch/latch, bldg 0314.										
Diagnostic Fee	\$240 TW Labor 3 hours @ \$ 80/hr										
Additional Labor Cost to Perform Repairs	\$640 TW Labor 8 hours @ \$ 80/hr										
Additional Material Cost to Perform Repairs	\$1333.16 <table border="1" style="margin-left: 20px;"> <tr> <td>Steel Door 35.5 x 83.375</td> <td>1</td> <td>\$1,269.68</td> <td></td> <td>\$1,269.68</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td></td> <td>\$63.48</td> </tr> </table>	Steel Door 35.5 x 83.375	1	\$1,269.68		\$1,269.68	Sales Tax				\$63.48
Steel Door 35.5 x 83.375	1	\$1,269.68		\$1,269.68							
Sales Tax				\$63.48							
Total Cost of Repair	\$2,213.16										



WORK ESTIMATE

CSS #:

21691

Work Order #:

11410

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.	Facility ID:	MD002
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	314
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and material to replace exterior main entry door. Door is in bad shape replacement is recommended.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			8	\$640.00
Steel Door 35.5 x 83.375	1	\$1,269.68		\$1,269.68
Sales Tax				\$63.48
Diagnostic Labor			3	\$240.00
SUB-TOTAL COSTS:		Materials Total	\$1,333.16	Labor \$880.00
		TOTAL		\$2,213.16



The Home Depot Special Order Quote

Customer Agreement #: H2501-125348

Printed Date: 11/20/2019

Customer: JOHNNY W BROWN

Address: 740 TRENTON AVE
SEVERNA PARK, MD
21146

Phone 1: 410-562-1511

Phone 2: 410-562-1511

Email: JOHNNYBROW@GMAIL.COM

Store: 2501

Associate: MITCHELL

Address: 601 NEW ORDNANCE RD
GLEN BURNIE, MD 21060

Phone: 410-553-9600

Pre-Savings Total: \$1,058.07

Total Savings: (\$0.00)

Pre-Tax Price: \$1,058.07

All prices are subject to change. Customer is responsible for verifying product selections. The Home Depot will not accept returns for the below products.



Catalog Version 45



Call Width = Custom
Call Height = Custom

Line Number	Item Summary	Was Price	Now Price	Quantity	Total Savings	Total Price
100-1	Slab Only 35.5 x 83.375 Material Type = Steel Door Layout = 5" x 20" Narrow Lite Handing/Swing = Left Hand Outswing	\$1,058.07	\$1,058.07	1	\$0.00	\$1,058.07
Unit 100 Total:		\$1,058.07	\$1,058.07		\$0.00	\$1,058.07

Begin Line 100 Description

---- Line 100-1 ----

Steel Doors Slab Only 35.5 x 83.375
Call Width = Custom
Call Height = Custom
Handing/Swing = Left Hand Outswing
Fire Rating = 90 Minute
Material Type = Steel
Door Thickness = 1 3/4"
Door Style = Flush w/Vision Lite
Door Layout = 5" x 20" Narrow Lite
Glass = Polished Wire Glass
Door Material Thickness = Medium Duty (18
Gauge)
Door Core = Steel Ribbed Core
Door Edge Construction = Lockseam
Door Cap = None

Measurements Taken From = Door
Hinge Prep = 4 1/2"
Hinge Type = Ball Bearing
Number of Hinge Cutouts = 3
Top of First Hinge = 7
Top of Second Hinge = 39.125
Top of Third Hinge = 71
Hinge Finish = Prime Coat Finish (USP)
Hinge Factory Installed = No
Door Closer = None
Locking Device = None
Type of Lock Prep = Horizontal Exit Device
Center Line of Strike Plate = 43.5
Exit Device Trim Prep = Lever

Kickplate = No
Peep Viewer = None
Magazine Slot = None
Saddle / Threshold Depth = 6"
Door Bottom Gasketing = None
Weather Stripping = None
Door Stop = None
Hardware Finish = Satin Chrome (US26D)
SKU = 113776
Vendor Name = S/O L.I.F INDUSTRIES, INC.
Vendor Number = 60014403
Customer Service = 1-516-390-6800
Catalog Version Date = 1/6/2017

End Line 100 Description



B314

**U.S ARMY
RESERVE CENTER**

