

Additional Funding Request

| | |
|---|---|
| VA006 | CSS# 21905 WO# 11237 Asset# NA |
| Description of Repairs | Labor to annual certification of 2 boilers at VA006. |
| Diagnosis: Initial Work Order | Boilers 1 and 2 need to be certified |
| Diagnostic Fee | \$0 |
| Additional Labor Cost to Perform Repairs | <p>\$ 766.50</p> <p>TW Labor \$80/hr x 4</p> <p>Argent – \$446.50</p> |
| Additional Material Cost to Perform Repairs | \$0 |
| Total Cost of Repair | \$ 766.50 |



WORK ESTIMATE

CSS #: **21905**

Work Order #: **11237**

Emergency

Urgent

Routine

| | | | | | |
|-------------------------|--|--------------------------|---|-------------|--|
| Company Name: | Tidewater, Inc. | | Facility ID: | VA006 | |
| Contractor POC: | Adam Colopy | | | | |
| Telephone No: | 740-819-6207 | | Building/Location; (e.g., Classroom/Room #) | Boiler Room | |
| E-Mail Address: | adam.colopy@tideh2o.net | | | | |
| Assigned Technician(s): | Bill Davis | <input type="checkbox"/> | | | |

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor to annual certification of 2 boilers at VA006.

| LABOR/MATERIAL | | MATERIAL/ SUB UNIT DOLLAR AMOUNT | LBR/HR \$80 | LINE ITEM TOTAL DOLLAR AMOUNT |
|------------------|-----------------|---|----------------|--|
| ITEM | QUANTITY | | | |
| Labor | | | 4 | \$320.00 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| SUB-TOTAL COSTS: | Materials Total | \$0.00 | Labor | \$320.00 |
| | TOTAL | | | \$320.00 |

Argent Inspections, Inc.

QUOTATION— TIDEWATER, INC.

55TH USARC REGION 5, ZONE 3 VA006 USARC CHARLOTTESVILLE BOILER INSPECTIONS

Date: 10/15/2019

Quotation #: 0225-191015-01

Customer ID: 0225

Ship To:

Tidewater, Inc.
Attn: Adam Colopy, FMP
3761 Attucks Drive
Powell, OH 43065

Respond To:

Argent Inspections, Inc.
133 Haywick Ct.
Charleston, SC 29414

| Quantity | Item | Units | Description | Unit Price | Total |
|---|------------|-------|---|------------|-------------------------------|
| 1 | Inspection | Job | Inspection of 2 boilers at USARC Charlottesville in addition to contracted inventory, travel expenses, preparation and submission of paperwork. | \$ 446.50 | \$ 446.50 |
| Notice: Lack of preparation or discovery of mechanical or electrical problems could require more time than scheduled for inspection, which may result in additional charges. | | | | | Total \$ 446.50 |

Phone: 843-763-3549
Fax: 843-408-4463
Cell: 843-817-6701
E-mail: geoff@argentinsp.com

Argent Inspections is a National Board Authorized Inspection Agency, and all inspections are performed by Commissioned In-Service Inspectors in accordance with the National Board Inspection Code, The ASME Boiler and Pressure Vessel Code, and the applicable Jurisdictional Requirements. Additionally, all inspectors are licensed to perform inspections by the State of South Carolina and have their credentials on file with NAVFAC