

Additional Funding Request

NY067	CSS# 22151 WO# 6037 Asset# NA				
Description of Repairs	Labor and materials to replace (2) circulating pumps in OMS shop for boiler.				
Diagnosis: Initial Work Order	OMS shop has a circulator pump that is not working and needs to be replaced				
Diagnostic Fee	\$160 TW Labor 2 hours @ \$ 80/hr				
Additional Labor Cost to Perform Repairs	\$640 TW Labor 8 hours @ \$ 80/hr				
Additional Material Cost to Perform Repairs	\$589.59				
	Circ Pump - Taco 007IFC	2	\$276.37		\$552.74
	Sales Tax				\$36.85
Total Cost of Repair	\$1,389.59				



WORK ESTIMATE

CSS #: 22151

Work Order #: 6037

Emergency ☐

Urgent ☒

Routine ☐

Company Name:	Tidewater, Inc.	Facility ID:	NY067
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	OMS
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	Patrick Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace (2) circulating pumps in OMS shop for boiler.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			8	\$640.00
Circ Pump - Taco 007IFC	2	\$276.37		\$552.74
Sales Tax				\$36.85
Diagnostic Labor			2	\$160.00
SUB-TOTAL COSTS:		Materials Total	\$589.59	Labor \$800.00
TOTAL			\$1,389.59	

CENTRAL WAREHOUSE SUPPLY
7852 West River Road
Baldwinsville, NY 13027
315-638-4162 Fax: 315-638-8635

10/28/2019
Quote #: 2030
Page: 1

Quoted To:
CASH SALE

Cust PO:	Terms:	Salesperson:			
Reference:	Ship Via:	Valid Through: 11/11/2019			
Stock Code	Description	Taxable	Quantity	Price	Extended
HYSI007-IFC	PUMP TACO 007-IFC WITH FLOW CHECK 3 SPEED FOR INFLOOR	Y	2.00	230.31	460.62

Sub: 460.62 Tax: 36.85 Shipping: 0.00 Total: 497.47



